

# Landscape Conservation

## Land Management Contractors

### Case Study –Track and Fencing Work QPWS - Moreton Island National Park

#### Project Objective

- Repair and rebuild walking tracks, install stairs and fencing

#### Project overview

- Cape Moreton walking track reconstruction
- Installation of steps and erosion control structures
- High quality fence installation
- Improvement of visitor safety
- Supply and installation of native plants

#### Challenges

- Short lead time for completion of works
- Limited budgets
- Poor soil conditions requiring extra engineering
- Isolated with extremely difficult access

#### Environmental benefits

- Reduction in erosion and sedimentation
- Protection of native vegetation
- Sustainable long term visitor use

For further information please  
contact us on  
(07) 3395 4176  
or

[info@landscapeconservation.com.au](mailto:info@landscapeconservation.com.au)

